

MARYLAND DEPARTMENT OF THE ENVIRONMENT

LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO.

774825

0365497
MDE TRACKING NO.

0314080339 013
MDE PROPERTY NO. (Include county code prefix.)

Robinson Darryl
OWNER NAME

1724 Druid Hill Ave.
Street Address

Baltimore
Unit No. City

21217
Zip Code

County

1920
Property Construction Date

The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.

INSPECTION CATEGORIES

☐ 1. Lead Free

Methods

- ☐ A. One Time Only
(Interior & Exterior)
OR
☐ B. Limited
(Interior Lead Free Only)
Passing Re-inspection
required no later than:
____/____/____
Number of Pre-1950
Lead Free Units
Number of Post-1949
Lead Free Units

☒ 2. Full Risk Reduction

Methods

- ☒ A. Dust Inspection
OR
☐ D. Dust Inspection
with Exterior Waiver
Passing Re-inspection (Form D and
Supervisor Statement of Work)
required no later than 04/30/____
unless otherwise noted in local code.
OR
☐ E. Dust Inspection with
Lead Free Exterior

☐ 3. Modified Risk Reduction

Methods

- ☐ B. Visual Inspection and Dust
Inspection
OR
☐ C. Visual Inspection and Dust
Inspection with Exterior Waiver
Passing Re-inspection (Form D and Supervisor
Statement of Work) required no later than
04/30/____ unless otherwise noted in local
code.
OR
☐ D. Visual Inspection and Dust
Inspection with Lead Free Exterior

☐ 5. Lead Safe

Methods

- ☐ A. Dust Inspection
OR
☐ B. Dust Inspection and Visual Inspection
OR
☐ C. Dust Inspection with Lead Free Exterior
OR
☐ D. Dust Inspection and Visual Inspection
with Lead Free Exterior
AND
Verification that windows are lead free or have
been treated so friction surfaces are lead free.

☒ PASSED Based on the findings of the attached inspection report(s), I certify that the property/unit meets the certification criteria at this time. (circle property or unit)