| MARYLAND DEPARTMENT OF THE ENVIRONMENT 813325 | | | |
|--|--|---|--|
| LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO. | | | |
| 256342 03-14-07-0319-004 RJ Holdings LLC MDE PROPERTY NO. (Include county code prefix.) OWNER NAME | | | |
| MDE TRACKING NO. , M | DE PROPERTY NO. (Include county | code prefix.) OWNE | RNAME |
| | Ave ABC | City Zip Code | Baltimore City 1900 County Property Construction |
| Street Address J | Unit No. | | |
| The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, or signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection. Inspectificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maxim penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794. INSPECTION CATEGORIES | | | |
| 1. Lead Free | 2. Full Risk Reduction | 3. Modified Risk Reduction | 5. Lead Safe |
| Methods | Methods | Methods | Methods |
| A. One Time Only (Interior & Exterior) OR B. Limited (Interior Lead Free Only) Passing Re-inspection required no later than:/ Number of Pre-1950 Lead Free Units Number of Post-1949 Lead Free Units | OR D. Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04/30/ unless otherwise noted in local code. OR E. Dust Inspection with Lead Free Exterior | B. Visual Inspection and Dust Inspection OR C. Visual Inspection and Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04/30/_ unless otherwise noted in local code. OR D. Visual Inspection and Dust Inspection with Lead Free Exterior | □ A. Dust Inspection OR □ B. Dust Inspection and Visual Inspection OR □ C. Dust Inspection with Lead Free Exterior OR □ D. Dust Inspection and Visual Inspection with Lead Free Exterior AND Verification that windows are lead free or hav been treated so friction surfaces are lead free. |
| PASSED Based on the findings of the attached inspection report(s), I certify that the property unit meets the certification criteria at this time. (circle property or unit) | | | |
| FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit) I certify that I inspected the above listed property/unit on 9/18/17 at 1:00 a.m./p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD. Tom Flukinger Fail 14594 7/08/18 100% Lead Typection 5 13641 6/1/18 | | | |
| Inspector's Name Inspector's Signature Accreditation No. Accreditation Exp. Date Inspection Contractor Name Accreditation No. Accreditation Exp. Date | | | |

Form Number: MDE 330, Revised: 04/2017 (copy distribution: original to owner; yellow to MDE; pink to tenant; goldenrod to inspection contractor)