MARYLAND DEPARTMENT OF THE ENVIRONMENT LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO. 812807						
				G & RESS	LLC	
0353696 MDE TRACKING NO.	MDE PROPERTY NO. (Inclu	de county code pr	efix.)	OWNER NAM		· · · · · · · · · · · · · · · · · · ·
313 SOUTH STICKER			LTIMORE 2122	3 BALT	IMPRIS CITY	1900
Street Address		t No. City		Code Cou	nty Prop	perty Construction Date
The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, origina signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.  INSPECTION CATEGORIES						
1. Lead Free	2. Full Risk Reduc	etion	3. Modified Risk Reduction	on	5. Lead Safe	
Methods	Methods		Methods		Metl	nods
A. One Time Only (Interior & Exterior) OR	A. Dust Inspection OR	В	Visual Inspection and Dust Inspection OR		. Dust Inspection	
☐B. Limited  (Interior Lead Free Only)  Passing Re-inspection required no later than: //	Passing Re-inspection (Form D Supervisor Statement of Work) required no later than 04 / 30 /	and Passi State 04/3	Visual Inspection and Dust Inspection with Exterior Waive ing Re-inspection (Form D and Superment of Work) required no later that 0/ unless otherwise noted in loc	ervisor	C. Dust Inspection w	R ith Lead Free Exterior R id Visual Inspection sterior
Number of Pre-1950 Lead Free Units Number of Post-1949 Lead Free Units	unless otherwise noted in local OR  E. Dust Inspection with Lead Free Exterior		OR  Visual Inspection <u>and</u> Dust Inspection with Lead Free Ex	beei	ification that window	ws are lead free or have surfaces are lead free.
PASSED Based on the findings of the attached inspection report(s), I certify that the property/unit meets the certification criteria at this time. (circle property or unit)						
FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)  I certify that I inspected the above listed property/unit on 10/2/17 at 2:00 a.m./p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.  Daviel Block Subtitle 8 of the Environment Article, Annotated Code of MD.						
DANIEL BLOCK DO Inspector's Name Inspector's Si	gnature Accreditation No.	Accreditation			16318 Accreditation No.	2-18-19 Accreditation Exp. Date