

MARYLAND DEPARTMENT OF THE ENVIRONMENT

864002

LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO.

MDE TRACKING NO. 349122
MDE PROPERTY NO. (Include county code prefix.) 030918 3953 029
OWNER NAME Awe! Aida Shewangizaw
Street Address 1604 E. 29th St.
Unit No. SFP **City** Baltimore **Zip Code** 21218 **County** Baltimore **Property Construction Date** 1922

The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors **must** mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.

INSPECTION CATEGORIES

<input type="checkbox"/> 1. Lead Free	<input checked="" type="checkbox"/> 2. Full Risk Reduction	<input type="checkbox"/> 3. Modified Risk Reduction	<input type="checkbox"/> 5. Lead Safe
Methods <input type="checkbox"/> A. One Time Only <i>(Interior & Exterior)</i> OR <input type="checkbox"/> B. Limited <i>(Interior Lead Free Only)</i> Passing Re-inspection required no later than: ____/____/____ Number of Pre-1950 Lead Free Units Number of Post-1949 Lead Free Units	Methods <input checked="" type="checkbox"/> A. Dust Inspection OR <input type="checkbox"/> D. Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04/30/____ unless otherwise noted in local code. OR <input type="checkbox"/> E. Dust Inspection with Lead Free Exterior	Methods <input type="checkbox"/> B. Visual Inspection and Dust Inspection OR <input type="checkbox"/> C. Visual Inspection and Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04/30/____ unless otherwise noted in local code. OR <input type="checkbox"/> D. Visual Inspection and Dust Inspection with Lead Free Exterior	Methods <input type="checkbox"/> A. Dust Inspection OR <input type="checkbox"/> B. Dust Inspection and Visual Inspection OR <input type="checkbox"/> C. Dust Inspection with Lead Free Exterior OR <input type="checkbox"/> D. Dust Inspection and Visual Inspection with Lead Free Exterior AND Verification that windows are lead free or have been treated so friction surfaces are lead free.

☒ **PASSED** Based on the findings of the attached inspection report(s), I certify that the property/unit meets the certification criteria at this time. (circle property or unit)

☐ **FAILED** Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)

I certify that I inspected the above listed property/unit on 1/24/19 at 10:30 a.m./p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Sean Williams *[Signature]* 15645 6/1/20 Sean Williams 15646 4/9/20
 Inspector's Name Inspector's Signature Accreditation No. Accreditation Exp. Date Inspection Contractor Name Accreditation No. Accreditation Exp. Date

MARYLAND DEPARTMENT OF THE ENVIRONMENT

892353

LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO.

304977

MDE TRACKING NO.

03 09 18 3953038

MDE PROPERTY NO. (Include county code prefix.)

Aida Sheungizau Ave 1

OWNER NAME

1622 E. 29th Street

Street Address

Unit No.

City

Zip Code

County

Property Construction Date

The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "9999" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.

INSPECTION CATEGORIES

<input type="checkbox"/> 1. Lead Free	<input checked="" type="checkbox"/> 2. Full Risk Reduction	<input type="checkbox"/> 3. Modified Risk Reduction	<input type="checkbox"/> 5. Lead Safe
Methods <input type="checkbox"/> A. One Time Only (Interior & Exterior) OR <input type="checkbox"/> B. Limited (Interior Lead Free Only) Passing Re-inspection required no later than: / / Number of Pre-1950 Lead Free Units Number of Post-1949 Lead Free Units	Methods <input checked="" type="checkbox"/> A. Dust Inspection OR <input type="checkbox"/> D. Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04 / 30 / unless otherwise noted in local code. OR <input type="checkbox"/> E. Dust Inspection with Lead Free Exterior	Methods <input type="checkbox"/> B. Visual Inspection and Dust Inspection OR <input type="checkbox"/> C. Visual Inspection and Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04 / 30 / unless otherwise noted in local code. OR <input type="checkbox"/> D. Visual Inspection and Dust Inspection with Lead Free Exterior	Methods <input type="checkbox"/> A. Dust Inspection OR <input type="checkbox"/> B. Dust Inspection and Visual Inspection OR <input type="checkbox"/> C. Dust Inspection with Lead Free Exterior OR <input type="checkbox"/> D. Dust Inspection and Visual Inspection with Lead Free Exterior AND Verification that windows are lead free or have been treated so friction surfaces are lead free.

☒ **PASSED** Based on the findings of the attached inspection report(s), I certify that the property/unit meets the certification criteria at this time. (circle property or unit)

☐ **FAILED** Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)

I certify that I inspected the above listed property/unit on 12/23/19 at 12:30 a.m. (p.m.) under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Inspector's Name

Inspector's Signature

Accreditation No.

Accreditation Exp. Date

Inspection Contractor Name

Accreditation No.

Accreditation Exp. Date