

MARYLAND DEPARTMENT OF THE ENVIRONMENT

LEAD PAINT RISK REDUCTION (MDE FORM 330)

INSPECTION CERTIFICATE NO. 1053151

0389152
MDE TRACKING NO.

0308181468 025
MDE PROPERTY NO.

Michael Lomont Smith
OWNER NAME

01903 E LANVALE ST
Street Address

Unit No.

Full Risk Reduction
Inspection Category

BALTIMORE
City

Baltimore city
County

Dust Inspection
Inspection Method

21213
Zip Code

1900
Construction Year

PASSED
Inspection Status

Re-Inspection required no later than
Certificate Expiration Date

Invalid

Invalidated Date

I certify that I inspected the above listed property/unit on 2/2/2023 10:00:00 AM under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Medhanie Maashio
Inspection Contractor Name

18121
Accreditation No.

3/8/2023
Accreditation Exp. Date

Medhanie Maashio
Inspector's Name

18122
Accreditation No.

3/8/2023
Accreditation Exp. Date



Inspection certificates with numbers under 1000000 are not original documents; they were issued on paper prior to implementation of this online system.

STATE OF MARYLAND