

MARYLAND DEPARTMENT OF THE ENVIRONMENT

LEAD PAINT RISK REDUCTION (MDE FORM 330)

INSPECTION CERTIFICATE NO. 649344

0310884
MDE TRACKING NO.

0315140010029
MDE PROPERTY NO.

OWNER NAME

1705 N MOUNT ST
Street Address

SINGLE
Unit No.

Full Risk Reduction
Inspection Category

BALTIMORE
City

Baltimore City
County

Dust Inspection
Inspection Method

21217
Zip Code

0
Construction Year

PASSED
Inspection Status

Re-Inspection required no later than Certificate Expiration Date

NO
Invalid

Invalidated Date

I certify that I inspected the above listed property/unit on 4/8/2014 12:00:00 AM under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Odell Bolden
Inspection Contractor Name

6832
Accreditation No.

7/25/2015
Accreditation Exp. Date

Odell Bolden
Inspector's Name

5977
Accreditation No.

7/25/2015
Accreditation Exp. Date



Inspection certificates with numbers under 1000000 are not original documents; they were issued on paper prior to implementation of this online system.

STATE OF MARYLAND