## MARYLAND DEPARTMENT OF THE ENVIRONMENT

LEAD PAINT RISK REDUCTION (MDE FORM 330)

INSPECTION CERTIFICATE NO. 1080727

0394250 MDE TRACKING NO.

0312143827 023 MDE PROPERTY NO.

**301 E 25TH ST LLC** 

Full Risk Reduction

OWNER NAME

00301 E 25TH ST Unit # 1A BALTIMORE MD 21218

Street Address

**Dust Inspection** 

Inspection Category

Inspection Method

**Baltimore** city

Construction Year County

> PASSED Inspection Status

1920

Re-Inspection required no later than

Certificate Expiration Date

Invalid

Invalidated Date

I certify that I inspected the above listed property/unit on 10/27/2023 7:30:00 AM under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Lead R Us, LLC

Inspection Contractor Name

Inspection Contractor Accreditation No.

1/17/2024

Inspection Contractor Accreditation Exp. Date

Corey Floyd

17820

17819

Inspector Name

Inspector Accreditation No.

1/17/2024

Inspector Accreditation Exp. Date

Inspection certificates with numbers under 1000000 are not original documents; they were issued on paper prior to implementation of this online system.

STATE OF MARYLAND