

MARYLAND DEPARTMENT OF THE ENVIRONMENT

LEAD PAINT RISK REDUCTION (MDE FORM 330)

INSPECTION CERTIFICATE NO. 1139562

0373164
MDE TRACKING NO.

27004
MDE PROPERTY NO.

GHUGLU, LLC
OWNER NAME

406 E Coldspring Lane Unit # 2nd Floor Baltimore MD 21212
Street Address

Baltimore city
County

1920
Construction Year

Full Risk Reduction
Inspection Category

Dust Inspection
Inspection Method

PASSED
Inspection Status

Re-Inspection required no later than

Certificate Expiration Date

Invalid

Invalidated Date

I certify that I inspected the above listed property/unit on 6/27/2025 4:15:00 PM under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Pro Star Inspections
Inspection Contractor Name

17282
Inspection Contractor Accreditation No.

8/1/2026
Inspection Contractor Accreditation Exp. Date

Sean Sherwood
Inspector Name

104367
Inspector Accreditation No.

8/1/2026
Inspector Accreditation Exp. Date



Inspection certificates with numbers under 1000000 are not original documents; they were issued on paper prior to implementation of this online system.

STATE OF MARYLAND